Ms. Kasey Ashley California Regional Water Quality Control Board North Coast Region 5550 Skylane Boulevard, Suite A Santa Rosa, California 95403

Subject: Results of August 2005 Groundwater Monitoring

Shoreline Development Property 2 T Street, Eureka, California

Dear Ms. Ashley:

This letter transmits results of groundwater monitoring performed in August 2005 at the Shoreline Development Property in Eureka, California (Figure 1). GeoSyntec Consultants prepared this report on behalf of Shell Oil Company.

In accordance with Monitoring and Reporting Program No. R1-2001-83 (M&R 83), issued on 30 July 2001 by the California Regional Water Quality Control Board, North Coast Region (RWQCB), annual groundwater monitoring was performed at the site in December 2004. The results were transmitted to the RWQCB on 14 January 2005¹. By letter dated 11 February 2005, the RWQCB provided comments on the 2004 Annual Report². In their comments, the RWQCB concurred with the recommendation to collect groundwater samples from wells MW-6 and MW-7 during August 2005 because a sample could not be collected during the December 2004 monitoring event due to standing water. This report documents the effort of the August 2005 groundwater monitoring event at the site.

¹ GeoSyntec Consultants, 2005, "Results of 2004 Annual Groundwater Monitoring," 14 January.

² California Regional Water Quality Control Board, North Coast Region (RWQCB), 2005, "Comments on Results of 2004 Annual Groundwater Monitoring," Shoreline Development, 2 T Street, Eureka, California, 11 February.

SITE SETTING

The 2.6-acre site is located at 2 T Street, in Eureka, California and is bounded on the north by Humboldt Bay. The site elevation is approximately 10 feet above mean sea level (msl). The site was formerly the location of a bulk petroleum storage facility that contained six aboveground storage tanks, five underground storage tanks and an unlined retaining basin. Currently, the site is unpaved and vacant.

Between 1995 and 1997, approximately 10,000 cubic yards (yd³) of hydrocarbon-impacted soil at the site was excavated from 5 areas in the southern portion of the site, treated on-site and then replaced in the excavations together with clean backfill. The soil data from the excavation indicated the soil cleanup goals were met with the excavation activities; however, the groundwater quality goal of 50 micrograms per liter (µg/L) for total extractable petroleum hydrocarbons (diesel-range hydrocarbons) was not met. In the Remedial Action Plan (RAP) for the site, Shell proposed monitored natural attenuation to address the diesel-range hydrocarbons present in groundwater³. In their approval of the RAP, the RWQCB issued M&R 83, which required groundwater monitoring on an annual basis to verify the groundwater remedy for the site⁴.

The monitoring well network at the site consists of six on-site monitoring wells (MW-1, MW-2, MW-3, MW-4, MW-6, and MW-7) and two off-site, upgradient monitoring wells (MW-9 and MW-10) installed in December 1991 and January 1994 at locations shown on Figure 2. Monitoring wells MW-5 and MW-8 were destroyed during soil excavation activities in 1995.

SAMPLING PROCEDURES

The August 2005 groundwater monitoring event was performed on 1 August 2005 and consisted of measuring water levels in the accessible site monitoring wells and collecting and analyzing groundwater samples from wells MW-1, MW-2, MW-6 and

³ Pacific Environmental Group, 1999, "Remedial Action Plan," Former Shell Bulk Fuel Terminal, 2 T Street, Eureka, California, Case No. 1THUO78, 6 July.

⁴ RWQCB, 2001, "Concurrence with Remedial Action Plan," 30 July.

MW-7. Blaine Tech Services, Inc. (Blaine Tech) of Sacramento, California performed the fieldwork and their sampling logs are provided in Attachment 1.

GROUNDWATER ELEVATION AND FLOW DIRECTION

Before measuring the depth to groundwater, Blaine Tech used an interface probe to evaluate the presence of floating product; none was detected in any of the wells. The groundwater elevation at the site ranged from 7.70 feet above mean sea level (msl) in monitoring well MW-10 to 5.06 feet above msl in monitoring well MW-1. Table 1 summarizes groundwater levels measured during sampling events since October 2001, including the current event. Groundwater elevation contours for the August 2005 sampling event are shown on Figure 2.

The groundwater flow direction for the August 2005 monitoring event is predominantly to the northeast. The average flow gradient is 0.0048 ft/ft (25.26 ft/mile). The historical groundwater flow direction has been typically to the north under a similar gradient.

ANALYTICAL RESULTS

Calscience Environmental of Garden Grove, California, provided all sample containers and analyzed the groundwater samples collected from monitoring wells MW-1, MW-2, MW-6 and MW-7. Calscience analyzed the samples for total petroleum hydrocarbon as diesel (TPHd) with and without silica gel cleanup using EPA Method 8015M. The TPHd analyses were run with silica gel cleanup to remove organic material that may influence the diesel concentration determination. The analytical laboratory report is provided in Attachment 2.

Analysis of TPHd without silica gel cleanup indicated TPHd was detected in MW-1, MW-2, MW-6 and MW-7 at concentrations of 630 micrograms per liter (μ g/L), 1000 μ g/L, 1900 μ g/L, and 1000 μ g/L, respectively. When the TPHd analysis was performed with the silica gel cleanup, the concentrations in MW-1, MW-2, MW-6 and MW-7 were 180 μ g/L, 440 μ g/L, 550 μ g/L, and 560 μ g/L, respectively. It appears that naturally occurring hydrocarbons contribute to the TPHd concentrations detected in the analyses performed without the silica gel cleanup.

QA/QC

GeoSyntec conducted a quality assurance/quality control (QA/QC) review of the analytical data. Data were reviewed for completeness, accuracy, precision, sample contamination, conformance with holding times, and detection limits within acceptable ranges. The results of the review indicate the data are of acceptable quality.

RESPONSE TO RWQCB COMMENTS

With the monitoring events in April and August 2005, GeoSyntec and Shell have addressed two of the comments provided by the RWQCB regarding the 2004 Annual Groundwater Monitoring Report: 1) monitoring wells MW-6 and MW-7 were sampled in April 2005 to serve as seasonal high groundwater samples from the rainy season (Comment #2); and 2) this current event was performed to evaluate the apparent increasing concentrations of TPHd (Comment #3). The RWQCB also commented on the anomalous groundwater elevation from MW-2 in December 2004 (Comment #5); after checking with the field personnel and reviewing the field logs, it appears the anomalous elevation is the result of a field transcription error.

To address the remaining comments, GeoSyntec proposes to:

- sample groundwater monitoring wells MW-1, MW-2, MW-3, MW-6, MW-7, MW-9, and MW-10 in December 2005 and report the results to the RWQCB;
- check status of MW-4 (bent stovepipe reported) and make recommendation whether to destroy;
- resurvey the existing groundwater monitoring wells in December 2005 and include the results in the groundwater monitoring report; and
- include a discussion of whether 50 μg/L is appropriate as the cleanup level for TPHd in groundwater at the site. For example, the Environmental Screening Level (ESL) from the San Francisco Bay RWQCB for TPHd is 640 μg/L for potential impacts on freshwater or marine aquatic habitats and non-drinking groundwater resources.

The report including the above information will be submitted to the RWQCB by 31 January 2005. If you have any questions or comments, please contact Ms. Campagna at (707) 399-7878 or the undersigned at (510) 836-3034.



Sincerely,

Susan H. Skoe, P.E. **Project Engineer**

T. Bue, for Carolyn Kneiblher, C.HG. Associate Hydrogeologist

Copy w/attachments to:

Ms. Carol Campagna, Shell Oil Company

Mr. James Clark, Humboldt County Health Department

Mr. Fred Griffith, CUE, IV, LLC

Ms. Linda Mackey-Taverner, SCS Engineers

Attachments:

Table 1 Groundwater Monitoring Results

Figure 1 Site Location Map

Figure 2 Analytical Results and Groundwater Elevation Contour Map -

August 2005

Attachment 1 Blaine Tech Field Report

Attachment 2 Calscience Analytical Data Report

P:\PRJ2003REM\Shell\Eureka\Groundwater Monitoring\2005\August\2005 August Sampling Report.doc





Table 1 **Groundwater Monitoring Results** Shoreline Development, Eureka, California

Well No.	Date	TOC Elevation (ft msl) ¹	Depth to Water (ft)	Groundwater Elevation (ft msl)	TPHd without silica gel (ug/L)	TPHd with silica gel (ug/L)
MW-1	Aug-05	8.84	3.78	5.06	630	180
	Apr-05		5.57	3.27		
	Dec-04		2.64	6.20	<500	<50
	Dec-03		2.10	6.74	190	84
	Dec-02		5.28	3.56	67	<50
	Oct-01		3.75	5.09	100	100
MW-2	Aug-05	9.48	3.80	5.68	1000	440
	Apr-05		1.67	7.81		
	Dec-04		0.43	9.05	< 500	<50
	Dec-03		1.72	7.76	520	120
	Dec-02		4.40	5.08	200	<50
	Oct-01		4.25	5.23	560	300
MW-3	Aug-05	9.16 ²	6.60	NE		
	Apr-05		4.72	NE		
	Dec-04		3.96	NE		
	Dec-03		4.27	NE		
	Dec-02		6.35	NE		
	Oct-01		7.80	NE		
MW-4	Aug-05	9.28 2	NS ³	NE		
11177	Apr-05	7.20	3.21	NE		
	Dec-04		3.11	NE		
	Dec-03	1	4.00	NE NE		
	Dec-02		7.04	NE NE		
	Oct-01		8.10	NE NE		
MW-6	Aug-05	9.59 ²	8.37	NE NE	1900	550
1V1 VV -O		9.39	10.09	NE NE	990	
	Apr-05			NE NE		170
	Dec-04		7.21	†	1,800	110
	Dec-03	1	6.64	NE	2,100	920
	Dec-02	1	7.79	NE	180	<50
	Oct-01		8.25	NE	410	200
MW-7	Aug-05	8.73	3.38	5.35	1000	560
	Apr-05		3.61	5.12	430	110
	Dec-04			NS	NS	NS
	Dec-03		2.18	6.55	1,200	410
	Dec-02		3.56	5.17	59	<50
	Oct-01		3.55	5.18	98	40
MW-9	Aug-05	10.81	3.13	7.68		
	Apr-05		1.16	9.65		
	Dec-04		1.20	9.61		
	Dec-03		1.76	9.05		
	Dec-02		3.22	7.59		
	Oct-01		3.90	6.91		
MW-10	Aug-05	10.81	3.11	7.7		
	Apr-05		1.41	9.40		
	Dec-04		0.85	9.96		
	Dec-03	1	1.68	9.13		
	Dec-02	1	3.23	7.58		
	Oct-01		4.15	6.66		

- Notes:


 1) Top of Casing (TOC) Elevation last surveyed October 1995

 2) Casing elevation in doubt; groundwater elevation not calculated

 3) Due to damaged standpipe & casing, the well was dry
 "--" Not Sampled
 NE Not Estimated
 TPHd Total Petroleum Hydrocarbons as diesel
 NS Not sampled

NS - Not sampled





Topo Source: U.S.G.S. 7.5 Minute Series,


Eureka, CA Quadrangle (1972) Contour Interval = 20 ft

SITE LOCATION MAP
SHELL SHORELINE DEVELOPMENT
EUREKA, CALIFORNIA





FIGURE NO.	1
PROJECT NO.	WR0575
DATE	NOVEMBER_2005
FILE NO.	SITE_LOCATION



<u>LEGEND</u>

MW−1
GROUNDWATER MONITORING WELL (MW−4 LOCATION APPROXIMATE)

MW−5
DESTROYED GROUNDWATER WELL

(5.06) GROUNDWATER ELEVATION IN FEET-MSL, 8/1/05

630/180 TPHd/TPHd WITH SILICA GEL CLEANUP CONCENTRATION IN GROUNDWATER (ug/L)

7.0

CASING ELEVATION IN DOUBT; WELL NOT USED IN CONTOURING

GROUNDWATER ELEVATION CONTOUR IN FEET-MSL

APPROXIMATE DIRECTION OF GROUNDWATER FLOW



0	30	60
SCAL	E IN	FEET

	GEOSYNTEC	Consultant
Timus,	GEOSYNTEC	Consultan

GROUNDWATER MONITORING RESULTS — AUGUST 2005 SHORELINE DEVELOPMENT PROPERTY 2 T STREET, EUREKA, CALIFORNIA

FIGURE NO.	2
PROJECT NO.	WR0575
DΔTF·	18 OCTOBER 2009

ATTACHMENT 1 BLAINE TECH FIELD REPORT

1680 ROGERS AVENUE

SAN JOSE, CALIFORNIA 95112-1105	-1105	` -	ANALYSIS TO DETECT	LAB	Calscience	# SHO
INC.	7771 0555	(dn uea		ALL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIMITS SET BY CALIFORNIA DHS AND	EET SPECIFICATIONS A NIA DHS AND	ND DETECTION
CHAIN OF CUSTODY BTS# 050501-BM2	Sì	r Gel Cla			☐ RWQCB REGION	EGION
Geosyntec Consultants	√INE	Silica		SPECIAL INSTRUCTIONS		
SITE Shoreline Development	\TNO:	som/w		Fax COC to Geosytes Consultanta Att.	Consultants Attac	5
2 T Street	√רד כ	v)(N		after log in Fax # 025 042 2266	Consultants Attin: Sus	an Skoe
Eureka, CA	√ ∃TI	ISI(mice 10g iii. F4A# 725	-943-2300	
₹ IIC	SOAMO)8) U -		Report to: Geosyntec Consultants Attn: Susan Skoe TPH-D with & without Silica Gel Clean up (lowest possoble detection limits)	Consultants Attn: Su t Silica Gel Clean up (san Skoe Iowest possoble
SAMPLE I.D. DATE TIME "S TOTAL)) = 0	HdT		ADD'I INEORMATION	OLITATA	
HW-1 8/1 1455 W 2		×			STATES CONDITION	LAB SAMPLE #
MW 2 1240 11		X				
1415		Y				
Must Mo		×				
Dens		×				
SAMPLING DATE TIME SAMPLING COMPLETED #//S /73° PERFORMED BY \(\overline{\ov	Huss			RESULTS NEEDED NO LATER THAN Sta	Standard TAT	
MELENSED BY MELENSED BY MELENSED BY	DATE	TIME	RECEIVED BY		DATE	TIME
RÉLEASED BY	рате	TIME	RECEIVED BY		DATE	TIME
RELEASED BY	DATE	TIME	RECEIVED BY		DATE	TIME
SHIPPED VIA	DATE SENT	TIME SENT	COOLER#			

WELLHEAD INSPECTION CHECKLIST

Client	Geosphec				_ Date	_8/i	105	
*.	s 27 5	! E	urcka					
Job Numbe	050801	- Busz		Tẹch	nician	Bu	1	
Well ID	Well Inspected - No Corrective Action Required	Water Bailed From Wellbox	Wellbox Components Cleaned	Cap Replaced	Lock Replaced	Other Action Taken (explain below)	Well Not Inspected (explain below)	Repair Order Submitted
MW-1		lock	not fo	met		_		
Mw-Z	1/2 6	orts stry			(Cop)	not fun	e +	·
MW-3		nolDine	Id f)				
MW-4	Stew	deipe o	· /	y cla	naged	(h. t)		
MW-6	3 der	Dipe	hol b	l				
MW-T		Missing	3/2 bdi					
MW-9	×							
MW-10		1/2 tob	s stopp	rcd				
		* .	//					
····								
··-								
NOTES:								
			war					
					,		-	_

Page ____ of ___

WELL GAUGING DATA

Project # 050801-But_ Date _	8/1/05	Client Geosyntec
Site Shareline Development		

			T	<u> </u>	Thickness	Volume of				
	:	Well		Depth to	of	Immiscibles			Survey	
	*** !! **	Size	Sheen/	Immiscible	j .		Depth to water	-		C/S
-	Well ID	(in.)	Odor	Liquid (ff.)	Liquid (ft.)	(ml)	(ft.)	bottom (ft.)	or TOC	
М	IW-1	4	,				3.78	1724	toc	3
M	lw-2	4					3,50	16.20	1	2
M	lw-3	4					6.60	21.63		
Н	lw-4*	4			~~~		DRY	4.60		
	Iwle	4					8.37	18.30		
-	lw-7	4					3,38	17.82		4
И	w9	3					3,13	1470		
М	w-10	3				·.	3,77	11.25		
					-		·			
1	x Mw	1 K	as a	clanage	d stan	d Dipe 1	- Casing	<i>(</i>		
	***************************************		-			,	J			

		***							The state of the s	

Blaine Tech Services, Inc. 1680 Rogers Ave., San Jose, CA 95112 (408) 573-0555

Project #:	0505	01-B	MZ_	Client:	Go	osvnte	.c		
Sampler:	Bu			Date:		8/1/05			
Well I.D.:	MW-	(Well Di	ameter	7	4	6 8	
Total Well		`	24	Depth to	o Watei	r (DTW):	3.7	75	
Depth to Fr	ree Product		A STATE OF THE STA	Thickne	Thickness of Free Product (feet):				
Referenced	l to:	(EVC	Grade	D.O. Meter (if req'd): YSI HACH					
DTW with	80% Recha	arge [(H	leight of Water	Column	x 0.20)) + DTW]:	C	2.47	
Purge Method:	Bailer Disposable B Positive Air I Electric Subn	Displaceme	/	Waterra Peristaltic etion Pump		Sampling N	Other:	Bailer Disposable Bailer Extraction Port Dedicated Tubing	
8.7 (1 Case Volume	(Gals.) X Speci	う fied Volum		Gals.	Vell Diamete 1" 2" 3"	0.04 0.16 0.37	Well E 4" 6" Other	Diameter Multiplier 0.65 1.47 radius ² * 0.163	
Time	Temp (For °C)	pН	Cond. (mS orus)	Turbi (NT	-	Gals. Rem	noved	Observations	
Kolli	59.9	7.4	8965	20	'e	9			
1648	58.5	73	7565	27	2	18	<u>.</u>		
1450	58.1	7.3	7513	21		7-Ce			
									
Did well de	ewater?	Yes (No	Gallons	actuall	y evacuate	ed: 2	l Co	
Sampling I	Date: 8/	105	Sampling Tim	e: 1U55	-	Depth to	Water	r: 6.21	
Sample I.D).: <u>Hu</u>	v-1		Laborate	ory:	Kiff Cals	Science	Other	
Analyzed f	or: TPH-G	BTEX	мтве трн-D	Oxygenat	tes (5)	Other:			
EB I.D. (if	applicable)):	@ Time	Duplica	te I.D. ((if applica	ble):		
Analyzed f	or: TPH-G	BTEX	MTBE TPH-D	Oxygenat	tes (5)	Other:			
D.O. (if red	q'd): Pi	re-purge:		mg/L	P	ost-purge:		mg/]	
O.R.P. (if r	req'd): Pi	re-purge:		mV	P	ost-purge:		mV	

Project #:	<u> </u>	01- Zu	12	Client:	Teasy.	ntee			
Sampler:		Bul		Date:	700 Sy.	5			
Well I.D.:	M	w2		Well Diame	eter: 2	3 4	○ 6 8		
Total Well	Depth (TD	١.	E. 20	Depth to W	ater (DT	W): 3.	Es		
Depth to F	ree Product			Thickness of Free Product (feet):					
Referenced	l to:	ØVC)) Grade	D.O. Meter (if req'd): YSI HACH					
DTW with	80% Recha	arge [(H	eight of Water	Column x 0	.20) + D7	[W]: 6	.69		
Purge Method:	Bailer Disposable B Positive Air I Electric Subn	Displaceme		Waterra Peristaltic tion Pump Well D		Other: Well) 4"	Disposable Bailer Extraction Port Dedicated Tubing		
1 Case Volume	(Gals.) X	<u>う</u> fied Volum	= <u>28</u> , <u>2</u> les Calculated Vo	- 11 4	0.16 0.37	6" Other	1.47 radius ² * 0.163		
Time [163]	Temp (For °C)	рН С е. С е	Cond. (mS) or μS)	Turbidity (NTUs) 25	Gals	Removed	Observations		
1653	Wello	66.4	913 Cens	24		9			
1635	58.0 united	6.4 bnefi	9071 y fer 80%	24	28	5.5			
Did well de	ewater?	Yes (No	Gallons acti	ually eva	cuated:	28.5		
Sampling I	Date: 8/1	105	Sampling Time	e: 1640	Dept	h to Wate	r: 6.69		
Sample I.D): Mx-2			Laboratory:	Kiff	CalScience			
Analyzed f	for: TPH-G	BTEX	мтве ТРН-Д	Oxygenates (:	5) Other				
EB I.D. (if	applicable)	•	@ Time	Duplicate I.	D. (if app	olicable):			
Analyzed f	for: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5) Other	;			
D.O. (if red	q'd): Pı	e-purge:		mg/ _L	Post-pu	rge:	mg/I		
O.R.P. (if 1	req'd): Pi	e-purge:		mV	Post-pu	rge:	mV		

Project #:	0508	201-13	112	Client:	Ge	esynte	e.		
Sampler:		Bul		Date:	છ	1/05			
Well I.D.:	Her			Well Di	iameter	r: 2 3	4)6 8	
Total Well	Depth (TD): /2	₹.30	Depth to	Depth to Water (DTW): 8,37				
Depth to F	ree Product			Thickne	ess of F	ree Produ			
Referenced	l to:	(PVC)	Grade	D.O. Meter (if req'd): YSI HACH					
DTW with	80% Recha	arge [(H	eight of Water	Column	x 0.20) + DTW]	: 10	.36	
Purge Method:	Disposable B Positive Air I Electric Subn	Displaceme nersible /	Other		, <u>Vell Diamet</u> 1" 2"	Sampling ter Multiplier 0.04 0.16	Other:	Bailer Disposable Bailer Extraction Port Dedicated Tubing Diameter Multiplier 0.65 1.47	
1 Case Volume	(Gals.) X Speci	fied Volum	es Calculated Vo	— 1	3"	0.37	Other	•	
Time	Temp For °C)	рН	Cond. (mS or as)	Turbi (NT	-	Gals. Rer	noved	Observations	
1616	Col.Co	7.4	3758	7/00	ර	6.5			
1618	58.7	7.3	3859	34/1	<u>'</u>	/3			
1620	58.0	7.3	3842	344	/	19.5	-		
	wa.ta	el bin	efly for E	0%					
Did well de	ewater?	Yes C	No	Gallons	actuall	ly evacuat	ed: /	9.5	
Sampling I	Date: 15/1	105	Sampling Tim	e: 162	5	Depth to	Water	T: 10.3C	
Sample I.D).: M	Ne		Laborat	ory:	Kiff O	Science	Other	
Analyzed f	or: TPH-G	BTEX	мтве (ТРН-D)	Oxygenat	tes (5)	Other:			
EB I.D. (if	applicable)		@ Time	Duplica	te I.D.	(if applica	able):		
Analyzed f	for: TPH-G	BTEX	MTBE TPH-D	Oxygenat	tes (5)	Other:			
D.O. (if red	q'd): Pi	re-purge:		mg/L	F	Post-purge:		mg/	
O.R.P. (if a	req'd): Pi	re-purge:		mV	F	Post-purge:		mV	

									2
Project #:	080B8	1- Bu	12	Client:	Ga	ssent	C		
Sampler:	Ž	Date:	8/,	1/05					
Well I.D.:	plu	Well Diameter: 2 3 (4) 6 8							
Total Well	Depth (TD): /z	7.82	Depth to	Water	(DTW):	.3	3E	
Depth to Fr	ee Product			Thickne	ss of F	ree Produ			
Referenced	to:	PVC	Grade	D.O. Mo	eter (if	req'd):		YSI	НАСН
DTW with	80% Recha	arge [(H	eight of Water	Column	x 0.20)	+ DTW]	6	.27	
Purge Method:	Bailer Disposable B Positive Air I Electric Subn	Displaceme		Waterra Peristaltic ction Pump	Vell Diamete	Sampling I	Other:	Ex Dec	Bailer posable Bailer ktraction Port dicated Tubing Multiplier
9.4 1 Case Volume	Gals.) XSpeci	5 fied Volum	$= \frac{28.2}{\text{Calculated V}}$	Gals.	1" 2" 3"	0.04 0.16 0.37	4" 6" Other	(0.65 1.47 radius ² * 0.163
Time	Temp	рН	Cond. (mS) or μS)	Turbi (NT	-	Gals. Ren	noved	O	bservations
1700	60.8	6.9	25.45	23		9.5			
1702	590	6.9	23,97	21		19		,	
1705	58.5	6.9	23.25			28.5			·
								·	
Did well de	ewater?	Yes (No	Gallons	actuall	y evacuat	ed: 2	28.5	
Sampling I	Date: g/	105	Sampling Tim	ie: /7/0)	Depth to	Water	r: (0.1	
Sample I.D):: _{[[]}	w-7		Laborate	ory:	Kiff Cal	Science	Othe	er
Analyzed f	or: TPH-G	BTEX	MTBE TPH-D	Oxygenat	tes (5)	Other:			
EB I.D. (if	applicable)):	@ Time	Duplica	te I.D. ((if applica	ble):	Dui	<u></u>
Analyzed f	or: TPH-G	BTEX	MTBE TPH-D	Oxygenat	tes (5)	Other:		SAME	
D.O. (if red	q'd): P	re-purge:		mg/L	P	ost-purge:			^{ing} /L
O.R.P. (if r	req'd): P	re-purge:		mV	P	ost-purge:			mV

SOURCE RECORD BILL OF LADING FOR NON-HAZARDOUS PURGEWATER RECOVERED FROM GROUNDWATER WELLS AT:

M Joe
Teessy
Client

Shaeline Development

Street Address Eureha

THE NON-HAZARDOUS PURGE- WATER WHICH HAS BEEN RECOVERED FROM GROUND- WATER WELLS IS COLLECTED BY THE CONTRACTOR, MADE UP INTO LOADS OF APPROPRIATE SIZE AND HAULED TO: City, State

The contractor performing this work is BLAINE TECH SERVICES, INC., 1680 Rogers Ave., San Jose, CA 95112 (phone [408] 573-0555).

WELL I.D. GALS.						any other adjustments /	loaded onto BTS vehicle #	
WELL I.D. GALS.	MW-1 126	WW. 1 28.5	MW-6 1 19.5	HW7 1 28.5		added equip.	TOTAL GALS. 105 RECOVERED 2.5	

******************************* signature ____ BTS event#

date

REC'D AT

time

unloaded by signature

ATTACHMENT 2 CALSCIENCE ANALYTICAL DATA REPORT





August 12, 2005

Susan Skoe GeoSyntec Consultants 475 14th Street, Suite 450 Oakland, CA 94612-1940

Subject: Calscience Work Order No.: 05-08-0326

Client Reference: Eureka 2T Street, Eureka, CA

Dear Client:

Enclosed is an analytical report for the above-referenced project. The samples included in this report were received 8/4/2005 and analyzed in accordance with the attached chain-of-custody.

Unless otherwise noted, all analytical testing was accomplished in accordance with the guidelines established in our Quality Assurance Program Manual, applicable standard operating procedures, and other related documentation. The original report of any subcontracted analysis is provided herein, and follows the standard Calscience data package. The results in this analytical report are limited to the samples tested and any reproduction thereof must be made in its entirety.

If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,

Calscience Environmental Laboratories, Inc.

Don Burley Project Manager

CA-ELAP ID: 1230 · NELAP ID: 03220CA · CSDLAC ID: 10109 · SCAQMD ID: 93LA0830

7440 Lincoln Way, Garden Grove, CA 92841-1427 · TEL:(714) 895-5494 · FAX: (714) 894-7501



Analytical Report



GeoSyntec Consultants 475 14th Street, Suite 450 Oakland, CA 94612-1940 Date Received: Work Order No: Preparation: Method: 08/04/05 05-08-0326 EPA 3510C DHS LUFT

Project: Eureka	2T Street, Eurek	a, CA						Page 1 of 3
Client Sample Number			Lab Sample Number	Date Collected	Matrix	Date Prepared	Date Analyzed	QC Batch ID
MW-1			05-08-0326-1	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
<u>Parameter</u>	j	<u>Result</u>	<u>RL</u>	<u>DF</u>	<u>Qual</u>	<u>Units</u>		
TPH as Diesel		630	50	1		ug/L		
Surrogates:		REC (%)	Control Limits		Qual			
Decachlorobiphenyl		98	51-141					
MW-1			05-08-0326-1	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
	The sample extract was s	•		-				
<u>Parameter</u>	<u>!</u>	Result	<u>RL</u>	<u>DF</u>	<u>Qual</u>	<u>Units</u>		
TPH as Diesel		180	50	1		ug/L		
Surrogates:		REC (%)	Control Limits		Qual			
Decachlorobiphenyl		97	51-141					
MW-2			05-08-0326-2	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
<u>Parameter</u>	<u>!</u>	Result	<u>RL</u>	<u>DF</u>	<u>Qual</u>	<u>Units</u>		
Parameter TPH as Diesel	_	Result 1000	<u>RL</u> 50	<u>DF</u> 1	<u>Qual</u>	<u>Units</u> ug/L		
			<u>—</u>		<u>Qual</u> <u>Qual</u>	' <u></u> '		
TPH as Diesel		1000	50			' <u></u> '		
TPH as Diesel <u>Surrogates:</u>		1000 REC (%)	50 Control Limits			' <u></u> '	08/11/05	050810B15
TPH as Diesel Surrogates: Decachlorobiphenyl MW-2	Γhe sample extract was s	1000 REC (%) 92	50 <u>Control Limits</u> 51-141 05-08-0326-2	08/01/05	Qual Aqueous	ug/L	08/11/05	050810B15
TPH as Diesel Surrogates: Decachlorobiphenyl MW-2 Comment(s): -T	Γhe sample extract was s	1000 REC (%) 92 subjected to	50 <u>Control Limits</u> 51-141 05-08-0326-2 Silica Gel treatment p	1 08/01/05 orior to analysi	Qual Aqueous s.	ug/L 08/11/05	08/11/05	050810B15
TPH as Diesel Surrogates: Decachlorobiphenyl MW-2 Comment(s): -T Parameter	Γhe sample extract was s <u>Γ</u>	1000 REC (%) 92 subjected to Result	50 Control Limits 51-141 05-08-0326-2 Silica Gel treatment p RL	1 08/01/05 orior to analysi <u>DF</u>	Qual Aqueous s.	ug/L 08/11/05 Units	08/11/05	050810B15



Analytical Report



GeoSyntec Consultants 475 14th Street, Suite 450 Oakland, CA 94612-1940

Date Received: Work Order No: Preparation: Method:

08/04/05 05-08-0326 **EPA 3510C DHS LUFT**

Project: Eureka 2T Street, Eure	eka, CA						Page 2 of 3
Client Sample Number		Lab Sample Number	Date Collected	Matrix	Date Prepared	Date Analyzed	QC Batch ID
MW-6		05-08-0326-3	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
<u>Parameter</u>	Result	<u>RL</u>	<u>DF</u>	Qual	<u>Units</u>		
TPH as Diesel	1900	50	1		ug/L		
Surrogates:	REC (%)	Control Limits		Qual			
Decachlorobiphenyl	110	51-141					
MW-6		05-08-0326-3	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
Comment(s): -The sample extract wa Parameter	s subjected t <u>Result</u>	o Silica Gel treatment <u>RL</u>	prior to analys <u>DF</u>	is. <u>Qual</u>	<u>Units</u>		
TPH as Diesel	550	50	1		ug/L		
Surrogates:	REC (%)	Control Limits		Qual			
Decachlorobiphenyl	111	51-141					
MW-7		05-08-0326-4	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
<u>Parameter</u>	Result	<u>RL</u>	<u>DF</u>	<u>Qual</u>	<u>Units</u>		
TPH as Diesel	1000	50	1		ug/L		
Surrogates:	REC (%)	Control Limits		Qual			
Decachlorobiphenyl	87	51-141					
MW-7		05-08-0326-4	08/01/05	Aqueous	08/11/05	08/11/05	050810B15
Comment(s): -The sample extract wa					Lloito		
Parameter TPH as Diesel	Result 560	<u>RL</u> 50	<u>DF</u> 1	<u>Qual</u>	<u>Units</u> ug/L		
Surrogates:	REC (%)	Control Limits	ı	<u>Qual</u>	ug/L		

Decachlorobiphenyl

86

51-141



Analytical Report



GeoSyntec Consultants 475 14th Street, Suite 450 Oakland, CA 94612-1940

Date Received: Work Order No: Preparation: Method:

Qual

08/04/05 05-08-0326 **EPA 3510C DHS LUFT**

Project: Eurel	ka 2T Street, Eureka,	CA						Page 3 of 3
Client Sample Numb	er		Lab Sample Number	Date Collected	Matrix	Date Prepared	Date Analyzed	QC Batch ID
DUP			05-08-0326-5	08/01/05	Aqueous	08/10/05	08/11/05	050810B15
<u>Parameter</u>	<u>Re</u> :	sult	<u>RL</u>	<u>DF</u>	<u>Qual</u>	<u>Units</u>		
TPH as Diesel	21	0	50	1		ug/L		
Surrogates:	RE	<u>:C (%)</u>	Control Limits		Qual			
Decachlorobiphenyl	95		51-141					
DUP			05-08-0326-5	08/01/05	Aqueous	08/10/05	08/11/05	050810B15
Comment(s):	-The sample extract was sub	jected to S	Silica Gel treatment p	prior to analysi	S.			
<u>Parameter</u>	Re	sult	<u>RL</u>	<u>DF</u>	<u>Qual</u>	<u>Units</u>		
TPH as Diesel	14	0	50	1		ug/L		

Method Blank		098-03-039-808	N/A	Aqueous	08/10/05	08/12/05	050810B15	
<u>Parameter</u>	<u>Result</u>	<u>RL</u>	<u>DF</u>	Qual	<u>Units</u>			
TPH as Diesel	ND	50	1		ug/L			
Surrogates:	REC (%)	Control Limits		Qual				
Decachlorobiphenyl	92	51-141						

Surrogates:

Decachlorobiphenyl

REC (%)

84

Control Limits

51-141



Quality Control - LCS/LCS Duplicate



GeoSyntec Consultants 475 14th Street, Suite 450 Oakland, CA 94612-1940 Date Received: Work Order No: Preparation: Method: N/A 05-08-0326 EPA 3510C DHS LUFT

Project: Eureka 2T Street, Eureka, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared	Dat Analy		LCS/LCSD Batcl Number	h
098-03-039-808	Aqueous	GC 23	08/10/05	08/12/	05	050810B15	
<u>Parameter</u>	LCS %	REC LCSD	%REC	6REC CL	<u>RPD</u>	RPD CL	Qualifiers
TPH as Diesel	108	104	.	60-132	4	0-11	

RPD - Rel



Glossary of Terms and Qualifiers



Work Order Number: 05-08-0326

<u>Qualifier</u>	<u>Definition</u>
*	See applicable analysis comment.
1	Surrogate compound recovery was out of control due to a required sample dilution, therefore, the sample data was reported without further clarification.
2	Surrogate compound recovery was out of control due to matrix interference. The associated method blank surrogate spike compound was in control and, therefore, the sample data was reported without further clarification.
3	Recovery of the Matrix Spike or Matrix Spike Duplicate compound was out of control due to matrix interference. The associated LCS and/or LCSD was in control and, therefore, the sample data was reported without further clarification.
4	The MS/MSD RPD was out of control due to matrix interference. The LCS/LCSD RPD was in control and, therefore, the sample data was reported without further clarification.
5	The PDS/PDSD associated with this batch of samples was out of control due to a matrix interference effect. The associated batch LCS/LCSD was in control and, hence, the associated sample data was reported with no further corrective action required.
Α	Result is the average of all dilutions, as defined by the method.
В	Analyte was present in the associated method blank.
С	Analyte presence was not confirmed on primary column.
E	Concentration exceeds the calibration range.
Н	Sample received and/or analyzed past the recommended holding time.
J	Analyte was detected at a concentration below the reporting limit and above the laboratory method detection limit. Reported value is estimated.
N	Nontarget Analyte.
ND	Parameter not detected at the indicated reporting limit.
Q	Spike recovery and RPD control limits do not apply resulting from the parameter concentration in the sample exceeding the spike concentration by a factor of four or greater.
U	Undetected at the laboratory method detection limit.
X	% Recovery and/or RPD out-of-range.
Z	Analyte presence was not confirmed by second column or GC/MS analysis.

BLAINE

1680 ROGERS AVENUE FAX (408) 573-7771 PHONE (408) 573-0555

LAB SAMPLE # BHS# 0946 TPH-D with & without Silica Gel Clean up (lowest possoble ALL ANALYSES MUST MEET SPECIFISATIONS AND DETECTION LIMITS SET BY CALIFORNIA DHS AND TIME 1570 TIME TIME Report to: Geosyntec Consultants Attn: Susan Skoe Fax COC to Geosytec Consultants Attn: Susan Skoe ☐ RWQCB REGION 8-4-05 CONDITION -SN/7/8 022 DATE DATE DATE Standard TAT Calscience (after log in. Fax # 925-943-2366 STATUS SPECIAL INSTRUCTIONS Csemple costudia ADD'L INFORMATION □ LIA □ OTHER detection limits) RESULTS NEEDED NO LATER THAN LAB ED BY RECEINED B CONDUCT ANALYSIS TO DETECT COOLER# RECEIVE 844 TIME SEN 1530 TPH-D (8015M)(w/woSilica Gel Clean up) TIME TIME TIME X X DATE SENT 84-8 3/2/05 DATE DATE C = COMPOSITE ALL CONTAINERS SAN JOSE, CALIFORNIA 95112-1105 CONTAINERS 050801-BM2 PERFORMED BY TOTAL 4 SAMPLING Shoreline Development Geosyntec Consultants MATRIX M=H⁵0 R= ROIF BTS# 16S5 1625 410 ٥ // TIME TROPY TIME Eureka, CA 2 T Street TECH SERVICES, INC. DATE DATE CHAIN OF CUSTODY α RELEASED BY RELEASED BY RELEASED BY SAMPLE I.D. COMPLETED SHIPPED VIA SAMPLING MW 2 etes-Co MW-1 CLIENT Mer SITE



WORK ORDER #:

05-08-0326

Cooler ____ of ___

SAMPLE RECEIPT FORM

CLIENT: BTS GLOSYNTEC	DATE: 8-4-05
TEMPERATURE SAMPLES RECEIVED BY:	
CALSCIENCE COURIER: Chilled, cooler with temperature blank provided. Chilled, cooler without temperature blank. Chilled and placed in cooler with wet ice. Ambient and placed in cooler with wet ice. Ambient temperature. °C Temperature blank.	LABORATORY (Other than Calscience Courier): °C Temperature blank. °C IR thermometer Ambient temperature. Initial:
CUSTODY SEAL INTACT:	
Sample(s): Cooler: No (Not Intact)	: Not Applicable (N/A): Initial:
SAMPLE CONDITION:	
Chain-Of-Custody document(s) received with samples	
COMMENTS:	